

General Environmental Incident Summary

Incident: 5237 **Date/Time Notice:** 9/26/2016 1140 **DEM Incident No:**
Responsible Party: Farmers Union Oil Company
Date Incident: 9/24/2016 **Time Incident:** 1205 **Duration:** 1 hours
County: Mercer **Twp:** 144 **Rng:** 88 **Sec:** 24 **Qtr:**
Lat: 47.27788 **Long:** -101.78150 **Method:** Interpolation from map
Location Description: Farmers Union Oil Company (Cenex) 1600 Hwy 49N Beulah ND 58523

Submitted By: Joe Fouhy **Affiliation:** General Manager
Address: 1600 Hwy 49N
City: Beulah **State:** ND **Zip:** 58523

Received By:

Contact Person: Joe Fouhy
1600 Hwy 49N
Beulah, ND 58523

Distance Nearest Occupied Building: 1 Feet **Release Contained:** Yes

Type of Incident: Plastic Tote Puncture

Description of Released Contaminant: used oil

Volume Spilled: 150.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Tote was punctured by a forklift when attempting to move tote

Risk Evaluation:

Minimal risk, erosion & leaching contained

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

potential impact is soil

Action Taken or Planned:

Spill was contained to our dirt driveway, loader has been used to scrape up contaminated soil. Oil sock has been placed around pile of dirt to prevent any further leaching. A Heavy equipment operator coming in tomorrow to remove soil and scrape deeper than we are able to with our equipment.

Wastes Disposal Location: Looking for recommendations from NDDOH, heavy equipment operator may be able to provide location for tillage/rolling into clean soil.

Agencies Involved:

Updates

Date: 9/26/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Spoke with the general manager at Farmers Union Oil Company/Cenex. I gave him a list of waste facilities where he could take the contaminated soil. Requiring further follow-up to check on remediation progress.

Date: 9/29/2016 **Status:** Inspection

Author: Crowder, Kory

Updated Volume:

Notes:

On location 9/29/2016, at 1:35 p.m. Release occurred on the south side of gas station. An area approximately 50 X 50 feet has new soil in place. There are no remaining impacts noticed at this time. No further follow-up required.